



# Layering Paint™ Basic Application

Products: Faux Effects Layering Paint™, Faux Effects Wood Wax™

Tools: Foam Brush, Terrycloth Towel, Soft Cheesecloth

step 1. Brush on Layering Paint™ "Tint Base" to seal surface.

*Allow to dry 1 hour*

step 2. Brush on Layering Paint™ accent color of choice.

*Allow to dry 1 hour*

step 3. Brush on next color of Layering Paint™ to sandwich the accent color. Additional color layers may be applied

step 4. Translucent when applied, Dries to a darker, opaque shade.

*Allow to dry 2-3 hours*

step 5. To achieve the distressed, worn look using a water dampened terrycloth towel, lightly rub through layers of paint a little at a time, to partially expose color(s) beneath. Distressed finish is revealed as it dries. Be careful not to over rub or too much paint will be removed.

*Allow to dry 2 hours*

step 6. Layering Paint must be sealed for protection. Using cheesecloth, apply an even coat of Faux Effects Wood Wax™ to seal and protect.

## Tips:

Always make a sample to ensure the desired result.

Mix thoroughly before each use.

Additional Layering Paint™ may be applied to achieve desired look.

Do not overwork Wood Wax™ as it dries quickly.



2700 Industrial Avenue Two, Fort Pierce, Florida 34946  
800-270-8871 - [www.fauxfx.com](http://www.fauxfx.com)  
©2020 Faux Effects International, Inc. All Rights Reserved

